Electrostatic reproduction made by the Eisenhower Library for preservation purposes.

Delivery, and suffered a fractured collar-bone and abrasions of the head and knee. Garford blew but petcock on account poor material which broke through ball, west of Valparaiso. G.M.C. Ambulance #39304 ran off road and overturned in ditch on account careless driving. Ambulance recovered by Class B #414668. Frame kinked in several places. At 3 p.m. planking on small steel bridge gave way. Fair and warm. Roads fair but dusty. Made 80 miles in 84 hours. Arrived Chicago Heights, Ill., 3 p.m.

July 20

Chicago Heights, Sunday rest period. Ordnance Observer spent the night at the Chicago Automobile Club, as guest of the Four Wheel Drive Auto Co. Had breakfast with Lr. K. M. Newbold at the Congress Hotel, followed by motor ride over Lake Shore Drive & thru Lincoln Park. Took Mr. Newbold out to camp to inspect Convoy, at noon. Class B trucks #47905, #47986, #48043 & #48047, Cadillac Touring Car #18852, and G.M.C. Ambulance #24212, to replace damaged Ambulance #39309, added to Convoy at this point. Sergt. 1/c T. E. Wood, Jr. did a f ew demonstration stunts with the Militor for the instruction and entertainment of the camp visitors. Several movie weekly camera men "shot" this exhibition, and also groups of the officers. Citizens of town took most of the enlisted men to their homes for Sunday dinner. Goodyear Band is placed at disposal of the Expedition Commander for the remainder of the trip. All necessary adjustments made.

SASIMO SAN

July 21

Departed Chicago Heights, 6:15 a.m. Class B truck #48043 had to be towed by Militor a short distance to loosen up stiff motor. Stopped 45 min. to repair fan belt on Class B. 12 mi. out. Dodge #110219 stopped to adjust dragging foot brake band, right side. At 14 mi. from Chicago Heights G.M.C. Ambulance #39303 stopped to clean dirty spark plugs. One Mack truck had trouble with magneto breaker points. Range & stack of second 2-wheel kitchen trailer drop off in street of Joliet, where Rotary Club & Red Cross Canteen Service served refreshments. At Plainfield, Garford 739733 breaks upper fan bracket support, allowing fan bracket to fall forward so that fan tore several holes in radiator. When 2 mi. east of Aurora, Militor returned 10 mi. to pick up this Garford. Lunch served at Aurora by Red Cross Canteen Service. Mack #51487 has engine trouble all day. Class B #414673 water pump becomes stuck on account scale lodging under blade. Fair and warm. Roads fair, but very dusty. Made 82 miles in 101 hrs. Arrived DeKalb, Ill. 5 p.m.

July 22

Departed DeKalb, 6:15 a.m. Militor started 7:15 a.m. towing Carford #39733. Mack #51481 had to stop at Creston on account motor overheating due to late spark and inefficient water pump. Near Ashton water pump on Class B #414673 again fails to function and motor runs hot. 12 mi. east of Dixon